

BELZONA PROTECTS LIKE NO OTHER

ID: 497



PROBLEM

Old containment's rubber liner had failed from use and UV damage. Protection of new containment was required for continued use of acid mix down plant.

APPLICATION SITUATION

Protect new containment for concentrated acid storage tanks

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-3 and TCC-15.

BELZONA FACTS

Storage of 98% sulfuric Acid and concentrated hydrochloric acid and mix down tanks for bottling of Muratic pool acid requires capacity for full containment of these acids as required by governmental mandates in many parts of the world.

INDUSTRY

General Industry

LOCATION

Chemical manufacturing company, Florida - USA

APPLICATION DATE

April 2005

PRODUCTS

Belzona 4141 (Magma-Build)
Belzona 4911 (Magma TX Conditioner)
Belzona 4311 (Magma CR1)

SUBSTRATE

Concrete

PHOTOS

1. General view of the area
2. Belzona 4911 and Belzona 4141 applied
3. Belzona 4311 coat interrupted
4. Belzona 4311 applied over night, completing the application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

