

BELZONA SEALS GLAZING BARS

ID: 4972



PROBLEM

Water was penetrating the joints between aluminum frame and glass due to failure of the original sealant.

APPLICATION SITUATION

Glazing section on the roof of the residential building

APPLICATION METHOD

Application was carried out in strict accordance with Belzona Know-How System Leaflet RPA-3.

BELZONA FACTS

Belzona was chosen by the owner of the building because the repair could be carried out quickly and with minimal disturbance for the tenants. It was a quick and cost effective repair.

INDUSTRY

Buildings & Structures

LOCATION

Residential building, Croatia

APPLICATION DATE

November 2013

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Aluminum and glass

PHOTOS

1. Damaged glazing section of the roof
2. Masking tape in place and Belzona 3921 conditioner applied
3. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

