


SUCCESSFUL BELZONA REFURBISHMENT OF GUTTER

ID: 4975



PROBLEM

The client has had consistent water ingress issues from the aluminium gutters, despite repeated attempts to seal the gutter joints and seams with silicone and bitumen products. The showroom area has suffered water damage on a regular basis.

APPLICATION SITUATION

Client is the owner of a large interior furnishings showroom, with the premises now approaching 15 years of age.

APPLICATION METHOD

After thorough cleaning and drying of the substrate, application was carried out according with Belzona System Leaflet RPA-6. Belzona 3921 (GSC surface conditioner) was used to give optimum adhesion and a fully reinforced system incorporating Belzona 9311 (Reinforcing sheet) in the Belzona 3111 first coat was applied.

BELZONA FACTS

After "quick fix" alternatives of silicone and bitumen patching had failed, the client realised a Project orientated approach with a reputable system applied to the entire 95lm of gutters would offer a long term solution, and thus result in the best value protection for his asset.

INDUSTRY

Buildings & Structures

LOCATION

Interior furnishings showroom, Northern Ireland

APPLICATION DATE

April 2014

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Powder Coated Aluminium

PHOTOS

1. Gutters before application
2. Conditioner applied
3. Completed system

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

