


BELZONA REPAIRS AND PROTECTS 35 YEAR OLD CHILLER

ID: 4978



PROBLEM

Tube sheet was badly corroded and gas leaks were occurring.

APPLICATION SITUATION

Chiller unit that was into its 35th year of service.

APPLICATION METHOD

Application carried out in accordance with Belzona Know How System Leaflets HEX-1 & HEX-3

BELZONA FACTS

The standard Belzona repair techniques sealed the gas leaks on the tube sheet and provided corrosion protection to allow the unit to continue in service for many more years. The end covers were also protected at the same time.

INDUSTRY

Heating, Ventilation & Air Conditioning

LOCATION

University Facility, Israel

APPLICATION DATE

2008

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Carbon Steel

PHOTOS

1. The York chiller unit
2. Tube sheet before application
3. Completed coating of the tube sheet
4. Close up of the coated tube sheet

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

