

STANDING WATER - NOT A PROBLEM WITH BELZONA

ID: 498



PROBLEM

Leaking gutters

APPLICATION SITUATION

Stainless steel gutters

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-7.

BELZONA FACTS

Gutters on roof were coated with "low bid" product. Subsequent leaks soon appeared. Client wanted a more durable solution and chose Belzona once again.

INDUSTRY

General Industry

LOCATION

Air Force Base, Texas - USA

APPLICATION DATE

March 2005

PRODUCTS

Belzona 3111 (Flexible Membrane)
Belzona 3921 (GSC Surface Conditioner)
Belzona 9311 (Membrane Reinforcing Sheet)

SUBSTRATE

Stainless Steel

PHOTOS

1. Gutters conditioned with Belzona 3921 and seams coated with Belzona 3111.
2. Seams coated with Belzona 3111.
3. First coat of Belzona 3111.
4. Second coat of Belzona 3111.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

