


BELZONA WAREHOUSE FLOOR

ID: 5



PROBLEM

Deteriorated floor was creating a safety hazard.

APPLICATION SITUATION

Floor in warehouse.

APPLICATION METHOD

The application was carried out in accordance Belzona Know-How Leaflet FPA-1.

BELZONA FACTS

This is a long term solution to the problem. After three years in operation, the floor is in excellent condition.

INDUSTRY

Chemical & Petrochemical

LOCATION

Chemical plant in Louisiana

APPLICATION DATE

April 1995

PRODUCTS

Belzona 4131 (Magma screed)

SUBSTRATE

Concrete

PHOTOS

1. Surface preparation to the damaged area in progress.
2. The completed repair.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

