


BELZONA 2111 (D&A HI BUILD ELASTOMER) SAVES UTILITY

ID: 503



PROBLEM

Inspection revealed severe corrosion in spots on floor. Customer needed fast, cost effective repair.

APPLICATION SITUATION

Rubber lined lime slurry tank

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-3.

BELZONA FACTS

Hot vulcanization and liner replacement had been considered but were judged too time consuming and costly. Belzona® 2111 was chosen for its great abrasion and chemical resistance, as well as its ease of application. Repair still in excellent condition after three years of service.

INDUSTRY

Power

LOCATION

Power Authority, San Antonio, Texas USA

APPLICATION DATE

2002

PRODUCTS

Belzona 2111 (D&A Hi Build Elastomer)
Belzona 2911 (QD Conditioner)

SUBSTRATE

Rubber

PHOTOS

1. Lime slurry tank showing corrosion in rubber liner
2. Another view of corrosion
3. Close up view of corrosion
4. Belzona 2111 patch complete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

