

BELZONA PROTECTS STADIUM

ID: 506



PROBLEM

Wall caps had deteriorated to the point of either needing repairing or replacing.

APPLICATION SITUATION

Stone wall caps

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet RPA-11.

BELZONA FACTS

Replacement cost in this situation was astronomical; the Belzona solution offered a cost effective alternative. The Belzona® 3111 was tinted to match the color of the original stone.

INDUSTRY

Buildings & Structures

LOCATION

St. Louis University, St. Louis, Missouri
USA

APPLICATION DATE

April 2005

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Stone

PHOTOS

1. Overall view of stands
2. Close up of typical damaged block
3. Completed south wall area
4. Completed north wall area

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

