

BELZONA SEALS LEAKS IN GLASS BLOCK WALL

ID: 507



PROBLEM

Severe leaks causing interior damage to the ceiling and walls.

APPLICATION SITUATION

External glass block wall at entrance to University

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-1.

BELZONA FACTS

Belzona® 3111 was applied from the top of the glass over deteriorated and leaking calking and attached to the concrete wall at the top. Over the last few years, several contractors had worked on the wall at great expense without solving the problem.

INDUSTRY

Buildings & Structures

LOCATION

St. Louis University - St. Louis, Missouri
USA

APPLICATION DATE

April 2005

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Concrete, sheetmetal and glass

PHOTOS

1. Close up of deteriorated calking
2. Overall view on east wall
3. Completed east wall
4. Completed south wall

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

