

BELZONA 4181 REPAIRS AND PROTECTS WATER TREATMENT PLANT FLOORS

ID: 510



PROBLEM

Acid and Caustic spills were eating into the rough brick floor. Environmental and safety concerns became critical.

APPLICATION SITUATION

Brick Floors in water treatment plant

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & FPA-3.

BELZONA FACTS

Client needed a solution to a containment problem. Area to be protected was uneven and rough. The mortar-like consistency of Belzona® 4181 made it ideal for this repair.

INDUSTRY

Buildings & Structures

LOCATION

Power Authority, San Antonio, Texas USA

APPLICATION DATE

January 2004

PRODUCTS

Belzona 4111 (Magma Quartz)

Belzona 4181 (AHR Magma Quartz)

SUBSTRATE

Brick and Concrete

PHOTOS

1. Demineralization chemical handling area
2. Area following surface preparation and cleaning
3. Belzona 4111 was used to patch holes in floor and curb area where appropriate
4. Finished project

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

