

CORRODED AND CRACKED PIPEWORK FIXED WITH BELZONA

ID: 5106



PROBLEM

The pipe had corroded and cracked, leaking 10% Sodium Hydroxide.

APPLICATION SITUATION

Pipework at global paints and coatings company.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet VPF-11. Surface preparation was carried out using an MBX Bristle Blaster as grit blasting was not an option. After stemming weep, the pipe was wrapped with Belzona 1161 incorporating Belzona 9341 (Reinforcement Tape).

BELZONA FACTS

The Belzona solution ensured the repair was carried out in as little amount of time as possible (just 4 hours), keeping downtime to a minimum.

INDUSTRY

General Industry

LOCATION

Manufacturing company, Slough, UK

APPLICATION DATE

May 2014

PRODUCTS

Belzona 1221 (Super E-Metal)
Belzona 1161 (Super UW-Metal)

SUBSTRATE

Steel

PHOTOS

1&2. Cracked and corroded pipework

3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

