

BELZONA WEATHERPROOFS TWO SUGAR SILOS

ID: 5175



PROBLEM

Infiltration of water into the tank through the porous concrete.

APPLICATION SITUATION

Two sugar silos within the sugar factory required weatherproofing

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet WPA-1. The work was completed by applying the system in vertical stripes of 6 meter width.

BELZONA FACTS

The Belzona 3111 system is proven to provide excellent long term weatherproofing of substrates. The application was carried out in 10 weeks with a team of 7 applicators. The silos have been revisited after 2 years and 6 years later, the application was still in perfect condition.

INDUSTRY

Food & Drink

LOCATION

Sugar factory, Northern France

APPLICATION DATE

2014

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Concrete

PHOTOS

1. General view of the sugar plant
2. On-going application
3. Finished application
4. 6 years after the application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

