


BELZONA REPAIRS DAMAGED CLIP JOINT

ID: 5181



PROBLEM

Clip joint had started to separate and tear.

APPLICATION SITUATION

Clip joint tear.

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SHM-4

BELZONA FACTS

Using Belzona 2311 SR Elastomer allowed the belt to be repaired in place during a lunch break eliminating downtime.

INDUSTRY

General Industry

LOCATION

BC, Canada

APPLICATION DATE

August 1996

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Mild steel and rubber.

PHOTOS

1. View of damaged clip joint
2. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

