

BELZONA REBUILDS SPLINE SHAFT

ID: 5182



PROBLEM

Replacement part not readily available and purchasing the entire assembly would have been very costly.

APPLICATION SITUATION

Replacement part was not readily available.

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet MPT-5

BELZONA FACTS

The use of Belzona allowed localized repairs to be executed with a minimal amount of downtime.

INDUSTRY

General Industry

LOCATION

BC, Canada

APPLICATION DATE

2005

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. Preparation of the damaged areas in progress
2. Splines reformed with Belzona 1111
3. Mounting flange in the process of being removed revealing rebuilt splines.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

