

BELZONA REPAIRS SCORED HYDRAULIC RAM

ID: 5183



PROBLEM

Hydraulic rams had been subjected to sever mechanical damage around the seal area, rendering them ineffective. This was the only heavy duty lifter used for loading on site. New ram was not immediately available.

APPLICATION SITUATION

Damaged hydraulic ram

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet MPT-3

BELZONA FACTS

Using Belzona 1221, an emergency repair material, allowed the rams to be rebuilt on site in a matter of hours.

INDUSTRY

Transport

LOCATION

BC, Canada

APPLICATION DATE

August 1996

PRODUCTS

Belzona 1221 (Super E-Metal)

SUBSTRATE

Chromed steel rod

PHOTOS

1. View of damaged ram
2. Damaged areas "V" out
3. Rebuilt with Belzona 1221
4. Completed repair.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

