

BELZONA REPAIRS RUBBER LINED SLURRY PUMP

ID: 5189



PROBLEM

A hole had worn into the rubber lining in a number of areas from the coal slurry and had started to erode the metal casing.

APPLICATION SITUATION

Rubber lining on a slurry pump

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SHM-11

BELZONA FACTS

The use of Belzona allowed localized repairs to be executed with a minimal amount of downtime.

INDUSTRY

General Industry

LOCATION

BC, Canada

APPLICATION DATE

1990

PRODUCTS

Belzona 2111 (D&A Hi-Build Elastomer)

SUBSTRATE

Steel/ Rubber

PHOTOS

1. Preparation of the damaged areas in progress
2. Preparation completed
3. Rubber liner rebuilt

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

