

BELZONA ELASTOMERS REPAIR CUT IN TIRE

ID: 5192



PROBLEM

Tire on earthmoving equipment had been badly damaged.

APPLICATION SITUATION

Damaged tire

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

BELZONA FACTS

Quick repairs to this issue prevented further damage to the underlying reinforcing plies, allowing the equipment to continue operating until a scheduled downtime. Belzona 2311 cures rapidly, reaching full mechanical strength in about 2 hours.

INDUSTRY

Mining & Quarrying

LOCATION

BC, Canada

APPLICATION DATE

June 1995

PRODUCTS

Belzona 2311 (SR Elastomer)

Belzona 2911 (Elastomer QD Conditioner)

SUBSTRATE

Rubber

PHOTOS

1. View of equipment and the extent of the damaged area
2. Surface around the damaged area prepared and coated with Belzona 2911
3. Damaged area sealed and rebuilt with Belzona 2211

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

