

BELZONA REBUILDS WORN CAT D9 SPLINESHAFT ASSEMBLY

ID: 5194



PROBLEM

The main drive spline on D-9 cat had worn loose over many years of service.

APPLICATION SITUATION

Worn spline shaft

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet MPT-5

BELZONA FACTS

With applications of Belzona, the option to disassemble can be done when required

INDUSTRY

Mining & Quarrying

LOCATION

BC, Canada

APPLICATION DATE

N/A

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. View of worn spline shaft assembly
2. Belzona 1111 Super Metal applied to worn splines
3. Components reassembled
4. The main framework that the Spline assembly is being bolted to

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

