

# BELZONA 2311 (SR ELASTOMER) USED FOR EMERGENCY REPAIRS

ID: 5197



## PROBLEM

A small cut had developed in a section of the belt

## APPLICATION SITUATION

Belt repair in gravel pit

## APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet SHM-1

## BELZONA FACTS

The use of Belzona 2311 allowed the yard to repair the damage before it became more serious. The quick setting properties of the repair material also allowed the repair to be completed during a lunch break ensuring no downtime.

## INDUSTRY

Mining & Quarrying

## LOCATION

BC, Canada

## APPLICATION DATE

2000

## PRODUCTS

Belzona 2311 (SR Elastomer)

## SUBSTRATE

Rubber

## PHOTOS

1. View of the cut in the belt
2. Initial preparation underway
3. The loose piece of belting has been cut away and area around it roughed up with a special roughing tool
4. Repair in progress

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

