



BELZONA ELASTOMERS USED TO PROTECT CONVEYOR BELT CLIPS

ID: 5200



PROBLEM

The fine gravel was constantly wearing out a clip joint

APPLICATION SITUATION

Belt clip

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SHM-1 and SHM-4

BELZONA FACTS

The use of the Belzona procedures enabled the clip joint to be permanently protected and the damaged section of the belt repaired at the same time

INDUSTRY

Mining & Quarrying

LOCATION

BC, Canada

APPLICATION DATE

1998

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Rubber and steel

PHOTOS

1. Preparation of the clip joint and damaged area in progress
2. Preparation completed
3. Area masked off and the prepared area conditioned with Belzona 2911 (QD Conditioner)
4. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

