

CENTRIFUGE ASSET RECOVERY

ID: 5206



PROBLEM

Corrosion of the internals lead to heavy pitting, and wall thickness of the carbon steel. It also led to the complete disintegration of the external water box and it's mount. The customer only had 4-5 days to make repairs or replace it with a new one. Lead time for a new centrifuge was weeks out, so a Belzona Turnkey application was their best option. The exterior was also protected with Belzona 5811, and 5111.

APPLICATION SITUATION

Centrifuge for process with high levels of brine present in the service causing internal, and external corrosion.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-3, and CEP-4. The interior pitting was repaired with Belzona 1111, and subsequently coated with Belzona 1321. The exterior was repaired in one area with Belzona 1111 and Belzona 9341, then coated with Belzona 5811 and Belzona 5111.

BELZONA FACTS

The Belzona refurbishment method allowed the customer to avoid a lengthy down time, and a \$75,000 replacement cost of a new centrifuge. Belzona recovered this asset for the customer for less than \$7,500 parts, material, and labor.

INDUSTRY

Chemical & Petrochemical

LOCATION

Houston, Texas, USA

APPLICATION DATE

July, 2014

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 9341 (Reinforcement Tape)
Belzona 1321 (Ceramic S-Metal)
Belzona 5811 (Immersion Grade)
Belzona 5111 (Ceramic Cladding)

SUBSTRATE

Carbon steel

PHOTOS

1. View of the interior bowl of the corroded centrifuge shortly after being taken out of service
2. Blasted internal and external substrate
3. Internal bowl coated with Belzona 1321
4. External repaired with Belzona 1111 and Belzona 9341, and coated with Belzona 5811 and Belzona 5111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

