

BELZONA REPAIRS AND PROTECTS DAMAGED DRAINS

ID: 5212



PROBLEM

The edges of the floor drain were breaking due to a combination of chemical attack and physical damage.

APPLICATION SITUATION

Floor drain.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1 for rebuilding worn or damaged floor surfaces. The surface was prepared by removing any existing coating and loose material or contamination. Belzona 4111 was applied to the floor drain edges with a stiff brush, in accordance with Belzona's Instructions For Use.

BELZONA FACTS

Belzona 4111 is resistant to all environmental attack and has outstanding chemical resistance. The system does not absorb water or chemicals and can resist pedestrian traffic in four hours.

INDUSTRY

General Industry

LOCATION

ON, Canada

APPLICATION DATE

June 2013

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

PHOTOS

1. Floor drain prior to application
2. Preparation in process
3. Application in process
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

