

BELZONA SAVES CENTRIFUGAL PUMP FROM REPLACEMENT

ID: 5221



PROBLEM

Erosion/Corrosion was eating away this water pump at a fruit processing company, causing it to pump less water than was required. It was then pulled from the scrap pile.

APPLICATION SITUATION

Centrifugal pump.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-10. The centrifugal pump was rebuilt to improve efficiency.

BELZONA FACTS

The customer was ready to replace the pump because it just wasn't pumping enough water. Belzona 1341 improved the volume, enough to satisfy their needs.

INDUSTRY

Food & Drink

LOCATION

WA, USA

APPLICATION DATE

1992

PRODUCTS

Belzona 1341 (Supermetalgilde)

SUBSTRATE

Cast Iron

PHOTOS

1. Damaged Cornell pump
2. Coating of impeller
3. Coating of pump casing

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

