

BELZONA 3411 SOLVES CORROSION ISSUE FOR A CHEMICAL PLANT

ID: 5222



PROBLEM

Customer has 52" flange on vessel that needs corrosion protection. Other vessels in unit have hefty fiberglass coverings that are difficult to remove and expensive to apply.

APPLICATION SITUATION

52" flange on vessel

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet GSS-11.

BELZONA FACTS

Customer saved several thousand dollars over previous FRP system with easier installation and now can inspect, or if vessel has to be opened, can use a box knife instead of a heat gun or grit blast equipment! Customer had seen Belzona 3411 advertised in Distributor Newsletter and thought it was worth trying this application. The unit was inspected 90 days after the install and it looked as good as it did on day 1.

INDUSTRY

Chemical & Petrochemical

LOCATION

Chemical Plant, South Louisiana, USA

APPLICATION DATE

June 2014

PRODUCTS

Belzona 3411 (Flange Encapsulating Membrane)
Belzona 8411 (Conditioner)
Belzona 9311 (Reinforcement sheet)

SUBSTRATE

Carbon Steel

PHOTOS

1. 52" Flange prepared for application, grit blasted
2. First coat of Belzona 3411
3. Second coat of Belzona 3411
4. Final sideview of flange

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

