

BELZONA REPAIRS RUBBER TRACK

ID: 5257



PROBLEM

The exposed fabric will wick in water and rot, causing the track to weaken and require replacement.

APPLICATION SITUATION

The rubber track was cut open, exposing the fabric.

APPLICATION METHOD

The cut on the track was positioned so the cut was open. The rubber was roughened and Belzona 2111 was applied in accordance with Belzona Know-How System Leaflet SHM-15.

BELZONA FACTS

Protecting the fabric has extended the life of the track, saving thousands of dollars and avoiding replacement.

INDUSTRY

General Industry

LOCATION

Washington, USA

APPLICATION DATE

1993

PRODUCTS

Belzona 2111 (D & A Hi-Build Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Caterpillar showing track
2. Close up of the cut in the track
3. Prepared and conditioned cut
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

