

BELZONA REPAIRS ENGINE CASING

ID: 5260



PROBLEM

The engine block had a large piece of the casing broken off.

APPLICATION SITUATION

Damaged engine casing.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet ENC-1. After the proper surface preparation, the two broken pieces were locked in place using studs and Belzona 1111 was applied.

BELZONA FACTS

Twenty dollars worth of Belzona 1111 saved the engine block from being scrapped. The customer was fully satisfied with the results.

INDUSTRY

General Industry

LOCATION

Washington, USA

APPLICATION DATE

1992

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Cast Iron

PHOTOS

1. Engine block showing missing pieces
2. Two pieces locked in place with studs
3. Completed application with Belzona 1111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

