

BELZONA IMPROVES SAFETY WITH NONSKID SURFACE

ID: 5263



PROBLEM

Ice build-up on the steps was causing slip problems. The chemical deicer was destroying the concrete.

APPLICATION SITUATION

Slippery steps.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. The surface was blasted to remove all surface laitence. Belzona 4411 was brushed onto the surface and Belzona 9221 was spread on top.

BELZONA FACTS

The nonskid surface remained perfect until the building was demolished over 20 years later.

INDUSTRY

Buildings & Structures

LOCATION

Washington, USA

APPLICATION DATE

1992

PRODUCTS

Belzona 4411 (Granogrip)

Belzona 9221 (Surefoot Aggregate White)

SUBSTRATE

Concrete

PHOTOS

1. Blasting the concrete
2. Brushing on Belzona 4411
3. Sprinkling on Belzona 9221
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.