


BELZONA KEEPS AIRPORT COOL WITH HEAT EXCHANGER REPAIR

ID: 5267



PROBLEM

Corrosion caused by the chemicals in the system were eating away the tube sheet and end cover.

APPLICATION SITUATION

Corroded heat exchanger.

APPLICATION METHOD

The tube sheet and end cover were blasted and coated with two layers of Belzona 1321. It was decided to not use corks because the tube sheet was small. The application was carried out in accordance with Belzona Know-How System Leaflets HEX-1 & HEX-2.

BELZONA FACTS

A new replacement heat exchanger was out of the question due to budget restraints. The cost to repair the equipment with Belzona was far less than the replacement costs.

INDUSTRY

Heating, Ventilation & Air Conditioning

LOCATION

Billings, MT, USA

APPLICATION DATE

1986

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Steel

PHOTOS

1. Corroded tube sheet
2. Brushing on Belzona 1321
3. Completed application on the tube sheet
4. Completed application of the coating on the end cover

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

