

BELZONA IMPROVES SAFETY WITH GRIP SYSTEM ON STEPS

ID: 5273



PROBLEM

Stick on strips had caused tripping problems.

APPLICATION SITUATION

Nonslip on football stadium steps.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. The step nosings were blasted. The nosings were masked off and Belzona 4411 was brushed on. Belzona 9221 was sprinkled on.

BELZONA FACTS

Stick on strips had proved to be ineffective, causing trip hazards. Belzona 4411 reduced the potential for accidents and provided an aesthetically pleasing finish.

INDUSTRY

Buildings & Structures

LOCATION

Montana, USA

APPLICATION DATE

1986

PRODUCTS

Belzona 4411 (Granogrip)

Belzona 9221 (Surefoot Aggregate White)

SUBSTRATE

Concrete

PHOTOS

1. Overview of football stadium
2. Nosings blasted and masked off
3. Brushing on Belzona 4411
4. Completed application, ready for repainting

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

