

BELZONA PROVIDES EMERGENCY REPAIR ON A WORN CONVEYOR BELT

ID: 5277



PROBLEM

A large hole had formed in this conveyor belt, causing an interruption in production.

APPLICATION SITUATION

Worn conveyor belt

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

BELZONA FACTS

A large hole on the conveyor belt threatened to interrupt production. The use of Belzona 2311 enabled maintenance and completed the necessary repair. Belzona reinforced the conveyor belt with a minimum amount of downtime and also prevented the loss of production.

INDUSTRY

General Industry

LOCATION

BC, Canada

APPLICATION DATE

September 2005

PRODUCTS

Belzona 2311 (SR Elastomer)

Belzona 2911 (Elastomer QD Conditioner)

SUBSTRATE

Rubber

PHOTOS

1. Damaged conveyor belt, ready for repair.
2. Close up of repair area showing the use of the Belzona mixing surface, which was positioned underneath the belt to act as a suitable temporary backing for the repair.
3. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

