

BELZONA REBUILDS ERODED KEEL COOLER

ID: 5283



PROBLEM

The keel cooler metal was suffering from corrosion pitting.

APPLICATION SITUATION

Eroded keel cooler

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SOS-1 and SOS-2.

BELZONA FACTS

As a leader in corrosion resistance coatings, Belzona repair materials are approved by many marine specifying authorities. Belzona 1311 rebuilt the keel cooler and Belzona 1321 protected the surface. Belzona provides an extend life time service for the keel cooler.

INDUSTRY

Marine

LOCATION

BC, Canada

APPLICATION DATE

May 2008

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Mild Steel

PHOTOS

1. View of corrosion.
2. Corroded and pitted areas rebuilt.
3. Completed application. Entire cooler surface protected.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

