

BELZONA PERFORMS A CLASSIC REPAIR

ID: 529



PROBLEM

A small crack had developed in the 2.8 litre engine casing of this 1951 David Brown Lagonda.

APPLICATION SITUATION

Engine casing on vintage car

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-1.

BELZONA FACTS

Belzona was chosen as being the quickest, simplest and cheapest method of conducting the repair. Other alternatives would have involved welding, which the client did not want to pursue due to the age of the casting. The repair needed to be carried out quickly as the car was to go on show the following day. The total cost was around £15 (\$28) to complete.

INDUSTRY

General Industry

LOCATION

Motor Enthusiast, Cheshire, England

APPLICATION DATE

April 2005

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 9341 (Reinforcement Tape)

SUBSTRATE

Cast Iron

PHOTOS

1. The engine block
2. The exterior of this fully restored classic car
3. The cars interior
4. The rear view of the car

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

