



BELZONA PROTECTS ACID VESSEL FROM CHEMICAL ATTACK

ID: 5306



PROBLEM

The acid had damaged the teflon coating.

APPLICATION SITUATION

Acid production vessel.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-3 for repairing/renewing damaged linings. Abrasive blasting was done to prepare the surface and Belzona 4311 was spray applied as a two coat system in accordance with Belzona Instructions For Use.

BELZONA FACTS

Belzona 4311 is a high performance, two-component barrier coating for protecting surfaces against the effects of chemical attack. This solvent free coating provides outstanding resistance to a broad range of chemicals, especially acids and alkalis.

INDUSTRY

General Industry

LOCATION

Niagara Falls, ON, Canada

APPLICATION DATE

June 2013

PRODUCTS

Belzona 4311 (Magma CR1)

SUBSTRATE

Steel

PHOTOS

1. Acid vessel
2. Prior to application
3. Application in progress
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

