

BELZONA SEALS HOLE IN GLASS LINED REACTOR

ID: 5307



PROBLEM

Lining had suffered from impact damage, resulting in a small hole in the lining. This made the reactor unusable.

APPLICATION SITUATION

Glass lined reactor.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-1 for sealing cracks, porous welds, bolted and riveted joints on tanks. The surface was ground. Belzona 1591 was applied with an applicator and brush in accordance with Belzona Instructions For Use.

BELZONA FACTS

The client used \$513.38 of Belzona 1591 for the repairs, saving more than \$600,000.00 in repair costs and many months of downtime. Belzona 1591 exhibits excellent erosion-corrosion resistance at elevated temperatures, through a unique binary curing mechanism. This mechanism allows application and cure at ambient temperatures with additional higher temperature resistance being achieved in service through post curing.

INDUSTRY

Power

LOCATION

Niagara Falls, ON, Canada

APPLICATION DATE

March 2013

PRODUCTS

Belzona 1591 (Ceramic XHT)

SUBSTRATE

Glass

PHOTOS

1. Overview of glass lined reactor
2. Glass lined reactor
3. Prior to application
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

