

BELZONA REPAIRS LEAKS IN WATER FEATURE

ID: 5315



PROBLEM

Leaks in the water feature.

APPLICATION SITUATION

Water feature.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6 for waterproofing gutters and standing water areas. The area was cleaned of any debris and blasted to prepare the surface. Belzona 3911 was applied to the concrete and Belzona 3921 was applied to the steel using a brush. Belzona 3111 was applied to the surface using a brush as a two coat system.

BELZONA FACTS

Belzona 3111 is a single component, solvent free, microporous coating for the long-term repair and protection of all types of roofs. This versatile liquid applied material provides outstanding weatherproofing and waterproofing properties with excellent protection against infrared and ultra violet radiation and provides long-term protection for 20 years plus.

INDUSTRY

Buildings & Structures

LOCATION

Toronto, ON, Canada

APPLICATION DATE

1987

PRODUCTS

Belzona 3111 (Flexible Membrane)
Belzona 3911 (PSC Surface Conditioner)
Belzona 3921 (GSC Surface Conditioner)

SUBSTRATE

Concrete and steel

PHOTOS

1. Water feature
2. Prior to application
3. Completed application
4. Water feature back online

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

