

BELZONA STEPS UP TO THE CHALLENGE

ID: 5319



PROBLEM

Spalled concrete around hand rail post.

APPLICATION SITUATION

Stairs to a municipal recreational centre.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1 for rebuilding worn and damaged floor surfaces. The step around the hand rail was prepared by removing any loose material. Belzona 4911 (Magma TX Conditioner) was applied using a brush and Belzona 4131 was applied directly on to the conditioned surface, initially spreading to a general level using normal screeding techniques and then using a metal straight edge.

BELZONA FACTS

Belzona 4131 is a two-component system for the repair and resurfacing of concrete and stonework. This high performance, non-porous resurfacing material provides excellent protection against the effects of abrasion, impact, vibration and chemical attack.

INDUSTRY

Buildings & Structures

LOCATION

Waterloo, ON, Canada

APPLICATION DATE

June 2011

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Prior to application
2. Preparation in process
3. Application in process
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA