


BELZONA SAVES A ROOF EXPANSION JOINT

ID: 5338



PROBLEM

The expansion joint on the roof of a bowling alley had split open, caused by movement through temperature variations.

APPLICATION SITUATION

Roof Expansion Joint

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet RPA-1.

BELZONA FACTS

The owner was planning to re-tar the entire roof, as recommended by the local roof contractor. Just part of one bucket of reinforced Belzona 3111 solved the problem with the building owner doing the application himself.

INDUSTRY

Buildings & Structures

LOCATION

Troy, MT, USA

APPLICATION DATE

1986

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Felt paper and tar

PHOTOS

1. & 2. With the pea gravel removed the problem is obvious
2. Problem solved.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

