


BELZONA: SWEET SUCCESS FOR CHOCOLATE MANUFACTURER

ID: 534



PROBLEM

Damaged lining caused by impact through years of service.

APPLICATION SITUATION

Granite lining (35-mm thick) on a chocolate mixing vessel.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-13.

BELZONA FACTS

Replacement costs on this piece of equipment were about €20,000 (\$16,000). The cost to repair the lining utilizing Belzona costs only €1,000 (\$1,200). The lining repaired with Belzona was in excellent condition after one year in service, and looks to provide many more years of cost-effective service. The customer has given Belzona the opportunity to protect other production vessels for long-term reliability and cost savings.

INDUSTRY

Commercial Facilities

LOCATION

Snack Food Producer in Serbia

APPLICATION DATE

January 2004

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Carbon steel

PHOTOS

1. Close-up of damaged lining
2. Mechanically prepared surface ready for Belzona
3. Completed application
4. Close-up of repaired lining detail

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

