

RIG BALLAST SYSTEM REPAIRED WITH BELZONA

ID: 535



PROBLEM

Severely corroded and leaking pipes in many sections of the ballast system which threaten the safety of the rig.

APPLICATION SITUATION

Pipes of the rigs ballast system.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a.

BELZONA FACTS

The application was carried out while the rig was still in operation saving large sum of money and time in work-stoppage. The repairs protected the rig from serious problems affecting its safety.

INDUSTRY

Oil & Gas

LOCATION

International deep water drilling company - Egypt

APPLICATION DATE

March 2002

PRODUCTS

Belzona 1121 (Super XL-Metal)
Belzona 1291 (ES Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. General view of the rig
2. Leakage of the ballast pipes of the rig
3. Repair completed
4. Another repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

