


BELZONA PROTECTS STERN TUBE

ID: 5353



PROBLEM

The US Army required standard protection against erosion and corrosion when the ship is dry docked.

APPLICATION SITUATION

Stern tube in a US Army Ship.

APPLICATION METHOD

The stern tube was grit blasted and then two coats of Belzona 5811 were brushed on. The application was carried out in accordance with Belzona Know-How System Leaflet SOS-2.

BELZONA FACTS

Belzona lasts through the expected time between inspections by the US Army.

INDUSTRY

Marine

LOCATION

Oregon, USA

APPLICATION DATE

2014

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Steel

PHOTOS

1. Stern of the ship
2. Inspecting the grit blast
3. First coat of black Belzona 5811
4. Second coat of gray Belzona 5811

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

