


BELZONA REPAIRS PURGE TANK

ID: 5358



PROBLEM

A purge tank was getting corroded to the point that hot water was seeping through small holes in the tank. Leakage and safety were a great concern.

APPLICATION SITUATION

Purge tank with hot water.

APPLICATION METHOD

The application was carried out in accordance to modified versions of Belzona's Know-How System Leaflets TCC-1 and TCC-15.

BELZONA FACTS

The use of Belzona to bond patches over most affected sections proved to be quicker and easier to do than welding. Replacing the tank would have been almost impossible due to costs.

INDUSTRY

General Industry

LOCATION

South Florida, USA

APPLICATION DATE

May 2014

PRODUCTS

Belzona 1511 (Super HT-Metal)
Belzona 5892

SUBSTRATE

Carbon Steel

PHOTOS

1. Condition of the tank
2. Tank after grit-blasting
3. Bonding metal patches using Belzona 1511
4. View of the tank after two coats of Belzona 5892

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

