

BELZONA STOPS LUBE LEAKS

ID: 5373



PROBLEM

The customer stored lube oil within a small containment area, when leaks would develop they would by-pass and go under the wall onto the ground outside of the containment area.

APPLICATION SITUATION

Concrete wall leaking lube oil

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-3.

BELZONA FACTS

The customer was using vital manpower and resources having to constantly clean-up the ground outside of the containment area, the Belzona application keeps the lube within the containment for easy clean-up.

INDUSTRY

Oil & Gas

LOCATION

Beaumont, Texas, USA

APPLICATION DATE

April 2014

PRODUCTS

Belzona 5811 (Immersion Grade)
Belzona 9331 (Reinforcing sheet)

SUBSTRATE

Concrete

PHOTOS

1. Before repair
2. During repair
3. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

