

BELZONA ENCAPSULATES A TRANSFORMER FAUCET

ID: 5381



PROBLEM

This leaking faucet was no longer needed, but in order to replace or plug it, the transformer would have to be taken off line and the entire 2000 gallons of oil would need to be drained resulting in lost revenue for this power company.

APPLICATION SITUATION

Leaking inspection faucet.

APPLICATION METHOD

The faucet was prepared with a grinder, then the active leak was stopped and sealed using Belzona 1291. Belzona 1161 was then used to encapsulate the entire faucet. Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11.

BELZONA FACTS

This repair used roughly \$30.00 USD of Belzona materials to stop the leak. With a potential 2 week long shut down resulting in unknown possible financial losses, using Belzona's leak solution systems was an easy winning situation saving the company both time and money.

INDUSTRY

Power

LOCATION

Lewiston, ID, USA

APPLICATION DATE

May 2014

PRODUCTS

Belzona 1291 (ES-Metal)

Belzona 1161 (Super UW-Metal)

SUBSTRATE

Brass and steel

PHOTOS

1. Prepared surface
2. Belzona 1291 applied in the end
3. Applying Belzona 1161
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

