

BELZONA IMPROVES WORKING CONDITIONS BY SEALING THE ROOF OF A CHOCOLATE FACTORY

ID: 5398



PROBLEM

Minor leaks were causing unsanitary conditions in the kitchen and the HVAC system could not keep up with the major temperature and humidity fluctuations causing discoloration in the highly decorative chocolates.

APPLICATION SITUATION

Poorly insulated roof

APPLICATION METHOD

The roof was pressure washed and the parapets were re-pointed with Belzona 4111. The roof was then completely sealed and protected with the Belzona 3111 system. The application was carried out in accordance with a modified version of Belzona System Leaflet RPA-10.

BELZONA FACTS

The owner remarked about the noticeable difference in temperature and humidity control after just the first coat of Belzona 3111 was applied.

INDUSTRY

Food & Drink

LOCATION

MO, USA

APPLICATION DATE

March, 2008

PRODUCTS

Belzona 3111 (Flexible Membrane)
Belzona 4111 (Magma-Quartz)

SUBSTRATE

Rubber

PHOTOS

1. Storefront image
2. The roof prepared and ready for application
3. Picture of the first 1/2 of sprayed Belzona 3111
4. Picture of finished installation of Belzona 3111, including repaired parapets

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

