

BELZONA WATERPROOFS FLASHINGS SAVING MILLIONS OF DOLLARS OF PRODUCT

ID: 5399



PROBLEM

The material used to seal the flashings on this firewall had become brittle and cracked, creating fissures for water to seep into the building. A solution was needed that was both flexible and UV stable to protect this pharmaceutical storage facility housing millions of dollars of product.

APPLICATION SITUATION

Roof flashings

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-8 using the fully reinforced Belzona 3111 system.

BELZONA FACTS

Due to past success with roof repairs for this pharmaceutical facility, Belzona was the confident choice. 850 linear feet of flashing was completely sealed and protected in two days. Inspected in 2012, the repair is still perfect.

INDUSTRY

Buildings & Structures

LOCATION

MO, USA

APPLICATION DATE

August, 2004

PRODUCTS

Belzona 3111 (Flexible Membrane)
Belzona 3921 (GSC Surface Conditioner)
Belzona 9311 (Reinforcement Sheet)

SUBSTRATE

Galvy/Metal

PHOTOS

1. Picture of Warehouse/Storage Structure
2. Picture of the damaged flashing in need of repair
3. Close-up of Belzona application
4. Completed Belzona repair of 80 linear feet of flashing

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

