

# BELZONA STOPS WATER DAMAGE TO AN OFFICE BUILDING

ID: 5400



## PROBLEM

The roof of this Customer Service Building was leaking, causing water damage to interior ceilings, walls, and expensive office equipment. Stop gap methods had failed and Belzona was chosen because of reputation and competitive pricing.

## APPLICATION SITUATION

Roof leaking

## APPLICATION METHOD

As shown above; a Belzona Surface Conditioner (purple) is first applied to the cleaned roof substrate. Next is a mesh coat of Belzona 3111 (gray) and a final coat of Belzona 3111 (white). The application was carried out in accordance with Belzona Know-How System Leaflets RPA-1 & RPA-8.

## BELZONA FACTS

This Belzona solution was attractive to this customer, in part, because no tear off of existing material was required. Thus the daily routine of the building and employees was unaffected. This roof will be maintenance free for many, many years.

## INDUSTRY

Commercial Facilities

## LOCATION

MO, USA

## APPLICATION DATE

October, 2005

## PRODUCTS

Belzona 3111 (Flexible Membrane)  
Belzona 3911 (PSC Surface Conditioner)  
Belzona 9311 (Reinforcing Sheet)

## SUBSTRATE

Rubber

## PHOTOS

1. View of the roof
2. Roof is prepared, conditioned & reinforcement done where needed
3. Belzona application commencing
4. Belzona application completed

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured  
under an ISO 9001 Registered  
Quality Management System.

[www.belzona.com](http://www.belzona.com)

