

SLIPPERY FLOOR DRAIN GETS BELZONA GRIP!

ID: 5407



PROBLEM

Concrete floor area around drain is very slippery with water & fish entrails. area sees both forklift and pedestrian traffic

APPLICATION SITUATION

The Customer needed a safety grip system for a slippery floor drain area in fish processing plant to avoid falls & injury

APPLICATION METHOD

The application was carried out in accordance to Belzona Know-How System Leaflets FPA-3 and FPA-8. Concrete cleaned thoroughly and one heavy coat of Belzona 5811 applied to floor area. Belzona 9211 (Supergrip Aggregate) was then broadcast onto uncured material to create an aggressive non-slip surface.

BELZONA FACTS

The Customer has been using Belzona repair materials for a number of years with good results. They easily choose this simple effective solution

INDUSTRY

Buildings & Structures

LOCATION

Bellingham, WA, USA

APPLICATION DATE

March 2013

PRODUCTS

Belzona 5811 (Immersion Grade)
Belzona 9211 (Supergrip Aggregate)

SUBSTRATE

Concrete

PHOTOS

1. Floor drain before the application
2. Thorough cleaning
3. Non-slip application of the floor drain is now complete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

