

BELZONA REPAIRS AND PROTECTS PUMP CASING

ID: 5415



PROBLEM

Pump casing was showing signs of degradation. This was from possible contamination during casting process.

APPLICATION SITUATION

Pump Casing

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-3, CEP-5.

BELZONA FACTS

A Belzona repair allowed the damaged areas to be quickly rebuilt and the casing protected from further bi-metallic erosion.

INDUSTRY

General Industry

LOCATION

BC, Canada

APPLICATION DATE

July 2002

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1341 (Supermetalgilde)

SUBSTRATE

Cast Iron

PHOTOS

1. View of casing showing damaged areas requiring rebuilding.
2. Application of 1st coat of Belzona 1341 in progress
3. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

