


BELZONA STOPS CLARIFIER LEAK EXTERNALLY

ID: 5422



PROBLEM

The leak was causing an environmental hazard as well as slippery walkways for pedestrians. The customer could not drain the unit. An external repair was needed to stop the leak.

APPLICATION SITUATION

Leak at clarifier wall

APPLICATION METHOD

Application was carried out using a modified version of Belzona Know-How System Leaflet VPF-11. Belzona 1291 was used to stop the initial leak, then Belzona 1161 was applied with Belzona 9341 reinforcement cloth over the entire area.

BELZONA FACTS

The customer had several failed attempts at the repair with other products, the Belzona solution had the repair complete within hours.

INDUSTRY

Water / Wastewater

LOCATION

Houston, Texas, USA

APPLICATION DATE

June 2014

PRODUCTS

Belzona 1291 (ES-Metal)
Belzona 1161 (Super UW-Metal)
Belzona 9341

SUBSTRATE

Concrete

PHOTOS

1. The application area before repair
2. The application area before the area
3. The area after the application and leak free

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

