

BELZONA REMEDIATES A DOCK AT A SUGAR REFINERY

ID: 5428



PROBLEM

Abuse from the metal tractor wheels combined with sugar and water causing concrete to be eroded. The dock was becoming unsafe for equipment and pedestrians.

APPLICATION SITUATION

Concrete Dock at a Sugar Refinery

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

Safety issues are being resolved. Belzona product is the first polymer repair product the Customer has used that didn't fail in the first few days of operation.

INDUSTRY

Sugar

LOCATION

South Louisiana, USA

APPLICATION DATE

August and September 2014

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 4911 (Magma TX Conditioner)
Belzona 9111 (Cleaner/Degreaser)

SUBSTRATE

Concrete

PHOTOS

1. Before the application in the first area
2. Application complete in the first area
3. Before the application in the second area
4. Application complete in the second area

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

